

Hoover East Side Ice Mitigation

OBSERVATIONS

February 2022

Summary

DCI Group was contracted in January of 2022 as Construction Manager for a potential project to mitigate ice build up on the East side of the Hoover Building. As part of this project DCI Group and the Department of Administrative Services made observations of the existing conditions during and after snow fall events, which are documented here.

PURPOSE OF POTENTIAL PROJECT

During and after snow events, ice and snow is building up on the existing curtain wall system then melting down the face of the curtain wall and dripping to the paver system below. The melt is then freezing again on the pavers causing ice buildup. In order to mitigate potential slip hazards the State of Iowa is blocking off this area of the walkway and heavily salting the pavers, which may result in premature deterioration to systems the salt comes in contact with.

SCOPE OF OBSERVATIONS

- Observer and document how snow and ice buildup were occurring on the existing curtain wall system during snow events.
- Observe and document how the snow and ice were melting

FINDINGS


Through multiple observations the following items were identified:


- The top of the curtain wall system consists of a slanted glass system. Snow is able to build up on the surface.
- Snow also is able to build up on the horizontal mullions.
- Warm conditioned air on the inside of the building, as well as general outside conditions, causes the snow build up to melt.
- It was observed that water will run down the face of the curtain wall system as well as within the vertical mullions.
- When this melt gets to the bottom of the curtain wall system it either freezes again, forming icicles, or falls to the patio system to freeze.
- On the West side of the building a similar issue appears to have been addressed utilizing a gutter system. If a similar resolution were pursued on the East side, the gutter system would need to include a downspout through the below paver patio system to connect to existing storm drains. Heat tape within the gutter system may also be warranted to avoid ice buildup.

PHOTOS

See photos of existing conditions on the following pages

Job #: 9258.00 DAS CC Hoover East Side Ice Mitigation 1305 E Walnut Street Des Moines, Iowa 50319





Description Description

Taken Date

02/25/2022 at 08:27 am

02/25/2022 at 09:13 am

Upload Date

Uploaded By Michael Steen

File Name

4D41EB62-BD60-429A-9302-C68...

Taken Date 02/25/2022 at 08:26 am


Upload Date

02/25/2022 at 09:13 am

Uploaded By
Michael Steen

File Name

A3F5003F-88<u>1D-4E</u>8A-90B2-9121...



Description

Taken Date

Upload Date

02/25/2022 at 08:24 am

02/25/2022 at 09:13 am

Uploaded By

Michael Steen

File Name

E5E21F91-AC27-4ED9-9086-31C4...

Description

Taken Date

02/25/2022 at 08:24 am

Upload Date

02/25/2022 at 09:14 am


Uploaded By

Michael Steen

File Name

DFD2B070-14F1-4B3A-ADB9-8A3...

Job #: 9258.00 DAS CC Hoover East Side Ice Mitigation 1305 E Walnut Street





Description


Taken Date

02/25/2022 at 08:24 am

Uploaded By Michael Steen

Upload Date File Name

02/25/2022 at 09:14 am ADE94CF0-35FC-4A30-91A3-D20...




Description

Taken Date

02/25/2022 at 08:22 am

Uploaded By Michael Steen

Upload Date File Name 02/25/2022 at 09:14 am DE3669EF-C6D7-46E6-AD92-2EE...



Description

Taken Date Uploaded By 02/25/2022 at 08:23 am Michael Steen

Upload Date File Name

02/25/2022 at 09:14 am D25D5FD2-4165-4C63-823F-1ED...



Description


Taken Date Uploaded By 02/25/2022 at 08:22 am Michael Steen

Upload Date File Name

02/25/2022 at 09:14 am 1CCC6DD5-DD40-44BC-A254-6D...

Job #: 9258.00 DAS CC Hoover East Side Ice Mitigation 1305 E Walnut Street Des Moines, Iowa 50319





Description

Description

Taken Date 02/25/2022 at 08:22 am

Upload Date 02/25/2022 at 09:14 am

Uploaded By Michael Steen

File Name


AFD00817-345D-49BC-89A6-88C...



Taken Date Uploaded By 02/25/2022 at 08:21 am Michael Steen

Upload Date File Name

02/25/2022 at 09:14 am 87570C10-1B3C-42A4-9013-ABB...



Description Description

Taken Date 02/25/2022 at 08:18 am

Upload Date 02/25/2022 at 09:14 am

Uploaded By Michael Steen


File Name BBF3B997-7958-4011-8204-6017... **Taken Date** 02/25/2022 at 08:18 am


Upload Date 02/25/2022 at 09:14 am **Uploaded By** Michael Steen

File Name

820027B8-6B1A-49B0-8514-8B8...

Job #: 9258.00 DAS CC Hoover East Side Ice Mitigation 1305 E Walnut Street Des Moines, Iowa 50319





Description

Taken Date 02/25/2022 at 08:18 am

Description

Upload Date

02/25/2022 at 09:14 am

Uploaded By Michael Steen

File Name

52E9B6ED-E5F0-437A-9703-5231...

Taken Date 02/25/2022 at 08:18 am

Upload Date

02/25/2022 at 09:14 am

Uploaded By

Michael Steen **File Name**

57A914B1-8DAA-4690-A088-59B...



Description

Taken Date 02/25/2022 at 08:18 am

Upload Date

02/25/2022 at 09:14 am

Uploaded By

Michael Steen

File Name

1074BF0F-7614-4FB4-A9C9-D5E6...

Description

Taken Date

02/25/2022 at 08:18 am

Upload Date

02/25/2022 at 09:14 am

Uploaded By

Michael Steen

File Name

372FA261-097D-45C1-95BD-C14...

Job #: 9258.00 DAS CC Hoover East Side Ice Mitigation 1305 E Walnut Street Des Moines, Iowa 50319





Description Description

Taken Date 02/25/2022 at 08:18 am

Upload Date

02/25/2022 at 09:14 am

Uploaded By Michael Steen

File Name

CFF9ACCA-01B5-4A32-BA63-568...

Taken Date 02/25/2022 at 08:17 am

Upload Date

02/25/2022 at 09:14 am

Uploaded By

Michael Steen

File Name

F43B5DF0-1D53-46E8-B54C-941...



Description

Description

Taken Date 02/25/2022 at 08:17 am

Upload Date

02/25/2022 at 09:14 am

Uploaded By Michael Steen

File Name 018049AF-99F5-4EB6-ABE6-9325...

Taken Date

02/25/2022 at 08:17 am

Upload Date

02/25/2022 at 09:14 am

Uploaded By


Michael Steen


File Name

305F85F8-C678-46E8-91FA-48BA...



Job #: 9258.00 DAS CC Hoover East Side Ice Mitigation 1305 E Walnut Street Des Moines, Iowa 50319





Description

Taken Date

02/25/2022 at 08:17 am


Upload Date

02/25/2022 at 09:14 am

Uploaded By Michael Steen

B456A76E-6A16-4B74-A9DA-0F2...

File Name



Description

Taken Date

02/24/2022 at 04:27 pm

Upload Date

02/25/2022 at 10:17 am

Uploaded By James Trower

File Name

IMG_0893.JPG



Description

Taken Date 02/24/2022 at 04:27 pm

Upload Date

02/25/2022 at 10:17 am

Uploaded By James Trower

File Name IMG_0892.JPG **Taken Date**

02/24/2022 at 04:26 pm

Upload Date 02/25/2022 at 10:17 am **Uploaded By**


James Trower

File Name

IMG_0889.JPG



Job #: 9258.00 DAS CC Hoover East Side Ice Mitigation 1305 E Walnut Street Des Moines, Iowa 50319



IMG_0884.JPG

Description

Description

02/25/2022 at 10:17 am

Taken Date Uploaded By
02/24/2022 at 04:26 pm James Trower
Upload Date File Name
02/25/2022 at 10:17 am IMG_0888.JPG

Taken Date Uploaded By
02/24/2022 at 04:24 pm James Trower
Upload Date File Name