



Edge of Dock, facing North. Precast stair (pre-failure) visible. 05/05/2017



Middle of dock, facing South. Shows where concrete has eroded.
05/05/2017



Dock area directly in front of double door entrance to building. Precast Stair (pre-failure) visible. Area where concrete eroded and filled with sand temporarily.
05/05/2017





