

- Parking lot repair with concrete Apx. 7,060 SF (highlighted in red)
- Exterior shell of garage replacement to include roof Apx. 5,100 SF, siding, and garage doors (highlighted in green)
- Interior renovation of classroom space Apx. 4,000 SF (highlighted in yellow)

