

Replace 7 existing Lennox RTU's with Lennox Enlight RTU's with the following factory installed options:

High Performance Economizer Factory Installed Single Enthalpy High Performance Economizer Direct Drive Supply Fan: Multi-Speed ECM Direct Drive Built-in BACnet IP and MS/TP (standard) Refrigerant R-454B Barometric Relief Damper Factory Installed Low Nox Factory Installed Combination Coil/Hail Guards Factory Installed Hinged Access Doors Factory Installed Environ Evaporator and Condenser Coil System Factory Installed 2" MERV8 - PLE Filter Factory Installed and condensate switch

Existing low and high voltage:

- replace existing tstats with Honeywell TH8321WF VisionPRO 8000 Smart Thermostats
- low voltage wiring to be replaced from RTU to T-stat if insufficient for operation
- if line voltage wiring is sufficient, use otherwise include replacement breakers and wiring as needed

The Lennox Enlight is equipped with a non-fused disconnect, if possible, I do not want to have an additional fused disconnect attached to the RTU. If there is no way around not having the fused disconnect on the RTU, the RTU needs to be ordered without the non-fused disconnect.

Gas:

- provide all materials needed to connect gas to replacement RTU to include replacing existing union and ball valve.

Roofing:

- include roof curb adapters
- include high wind hold down brackets
- penetrations needing sealed or repairs needing made from installation should be compatible with Duro Last Inc. roofing systems.
- I have utilized CentiMark Roofing in the past. Contact information Zac Franke (402)-650-0633