## RFP 927900-01 Attachment - Woodward Resource Center Building Details

	# of	Gross Area	Age (Year of	
Building Name	Floors	SF	Construction)	Floor plans available?
Administration #1	2		1917	PDF Fire Alarm as-builts
		,		Yes (scanned original plans, some documentation of
Westwood (Can Redemption) #2	4	35,000	1936	modifications) and pdf Fire Alarm as-builts
Larches #3	4	35,000	1929	PDF Fire Alarm as-builts
Myers Hall #6	2	28,312	1930	PDF Fire Alarm as-builts
				Yes (scanned original plans, some documentation of
Employees Building #7	2	41,475	west	modifications) and pdf Fire Alarm as-builts
				Yes (scanned original plans, some documentation of
101 Cherry Lane	1	6,000	1978	modifications) and pdf Fire Alarm as-builts
				Yes (scanned original plans, some documentation of
101 Franklin	1	6,000	1978	modifications) and pdf Fire Alarm as-builts
			1070	Yes (scanned original plans, some documentation of
103 Cedar	1	6,000	1978	modifications) and pdf Fire Alarm as-builts
102 Charm Lana	1	C 000	1070	Yes (scanned original plans, some documentation of
103 Cherry Lane	1	6,000	1978	modifications) and pdf Fire Alarm as-builts Yes (scanned original plans, some documentation of
103 Franklin	1	6,000	1978	modifications) and pdf Fire Alarm as-builts
103 FIBIIKIIII	1	0,000	1370	Yes (scanned original plans, some documentation of
104 Cherry Lane	1	6,282	1978	modifications) and pdf Fire Alarm as-builts
104 CHETTY Edite		0,202	1370	Yes (scanned original plans, some documentation of
104 Franklin	1	6,000	1978	modifications) and pdf Fire Alarm as-builts
		3,000		Yes (scanned original plans, some documentation of
105 Cherry Lane	1	6,282	1978	modifications) and pdf Fire Alarm as-builts
,				Yes (scanned original plans, some documentation of
105 Franklin	1	6,282	1978	modifications) and pdf Fire Alarm as-builts
				Yes (scanned original plans, some documentation of
107 Cherry Lane	1	6,000	1978	modifications) and pdf Fire Alarm as-builts
				Yes (scanned original plans, some documentation of
107 Franklin	1	6,000	1978	modifications) and pdf Fire Alarm as-builts
				Yes (scanned original plans, some documentation of
108 Franklin	1	6,000	1978	modifications) and pdf Fire Alarm as-builts
100 5	4	6 202	4070	Yes (scanned original plans, some documentation of
109 Franklin	1	6,282	1978	modifications) and pdf Fire Alarm as-builts Yes (scanned original plans, some documentation of
200 Franklin	1	6,000	1079	modifications) and pdf Fire Alarm as-builts
200 FIAIIKIIII	1	0,000	1976	Yes (scanned original plans, some documentation of
201 Cedar	1	6,000	1978	modifications) and pdf Fire Alarm as-builts
201 00001		0,000	1370	Yes (scanned original plans, some documentation of
201 Franklin	1	6,000	1978	modifications) and pdf Fire Alarm as-builts
				Yes (scanned original plans, some documentation of
202 Franklin	1	6,282	1978	modifications) and pdf Fire Alarm as-builts
				Yes (scanned original plans, some documentation of
202 Pine	1	6,000	1978	modifications) and pdf Fire Alarm as-builts
				Yes (scanned original plans, some documentation of
203 Franklin	1	6,282	1978	modifications) and pdf Fire Alarm as-builts
				Yes (scanned original plans, some documentation of
204 Pine	1	6,282	1978	modifications) and pdf Fire Alarm as-builts
204 8:			1070	Yes (scanned original plans, some documentation of
301 Pine	1	6,000	1978	modifications) and pdf Fire Alarm as-builts Yes (scanned original plans, some documentation of
202 Pin -	4	6 000	4070	
302 Pine	1	6,000	19/8	modifications) and pdf Fire Alarm as-builts Yes (scanned original plans, some documentation of
303 Pine	1	6,000	1078	modifications) and pdf Fire Alarm as-builts
303 FINE	1	0,000	13/0	Yes (scanned original plans, some documentation of
304 Pine	1	6,000	1978	modifications) and pdf Fire Alarm as-builts
30 T I IIIC	1 -	0,000	1-5/0	mounications) and partific Alarm as-bullts